KOKU-KU-KI-1175

No. TCD-4114A -2006

Date of Issue: March 14, 2006

## Japan Civil Aviation Bureau

## TAIKUSEI-KAIZEN-TSUHO

## **Airworthiness Directive**

The undermentioned examinations or modifications are mandatory.

- 1. Applies to: Kawasaki Model BK117, BK117A-3, BK117A-4, BK117B-1, BK117B-2 and BK117C-1 with Main Rotor Blade, all P/N
- 2. Compliance is required as indicated, unless already accomplished.

  To prevent detachment of the balance weight from main rotor blade which could result in extraordinary vibration, accomplish the following.
- 2.1 Before next flight, after the effective date of this AD, revise the KHI-BK117 Maintenance Manual, so that the manual contains at least revision no. 14 for KHI-BK117, BK117A-3, BK117A-4, BK117B-1 and BK117B-2 and revision no. 2 for KHI-BK117C-1 respectively.
- 2.2 Perform the inspection in accordance with the inspection interval and method mentioned in the KHI-BK117 Maintenance Manual revised by section 2.1.
- 2.3 If the inspection results are out of the allowable limit which is mentioned in the KHI-BK117 Maintenance Manual, contact the KHI Customer Service and prohibit the flight until doing action per a method advised by the KHI.
- 2.4 An alternative means of compliance with this AD may be used, if approved by the Director-General of JCAB.

## 3. Remarks

- 3.1 This AD becomes effective on March 28, 2006.
- 3.2 Kawasaki Service Bulletin No. KSB-117-115A dated January 27, 2006

and later JCAB-approved revisions pertain to this subject.				
3.3 This AD supersede	es the AD No.	TCD-4114-94, N	o. TCD-4114-1-2003 a	$\mathbf{nd}$
No. TCD-4114-2-2004.				

This is the English translation. In case of any difficulty, refer to the Japanese original text.