

KU-KEN-569

No.TCD- 631B-78

Date Aug. 28, '78

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Fuji Model FA-200 Series Airplanes

2. Compliance required as indicated

To prevent malfunction of the fuel quantity indicator due to failure of the transmitter, inspect the fuel quantity indicator, unless already accomplished, in accordance with Fuji Heavy Industries Service Bulletin No. FAS-005C dated April, 20, 1978 or later JCAB approved revisions.

If malfunction is found as a result of the inspection, replace the transmitter with a serviceable one and repeat the inspection in accordance with the above Service Bulletin.

3. Remarks

3.1 Effective date: August 28, 1978

3.2 Fuji Heavy Industries Service Bulletin No. FAS-005C covers this subject.

3.3 This AD supersedes TCD-631A-70