

KU-KEN-522

No.TCD-1094A-76

Date Sep. 6, 1976

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

Mitsubishi Model

1. Applies to: MU-2B-10/-15/-20/-26: S/N 005 thru 326
 MU-2B-30/-35/-36: S/N 501 thru 675

2. Compliance required as indicated

To prevent the failure of the flap jack screw, unless already accomplished, within 100 hour's time in service after the effective date of this AD, inspect and take necessary actions in accordance with Mitsubishi MU-2 Service Bulletin No. 167B dated July 26, 1976 or the later JCAB approved revisions.

3. Remarks

- 3.1 Effective date: Sep. 29, 1976
- 3.2 Mitsubishi MU-2 Service Bulletin No. 167B dated July 26, 1976 or the later JCAB approved revisions pertain to this subject.
- 3.3 This Airworthiness Directive supersedes TCD-1094-75