KU-KEN-1345

No.TCD 2856-87

Date October 29 1987

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

## Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

- 1. Applies to: Mitsubishi MU-2B-30/-35: S/N 502 thru 651 and 653, equipped with Bendix M4C Autopilot System.
- 2. Compliance required as indicated, unless already accomplished.

  To standardize the way to disengage the autopilot system, accomplish the following:

Within next 200 flight hours in service after the effective date of this AD, relocate and replace the disconnect switches of Bendix M4C autopilot system in accordance with Mitsubishi MU-2 Service Bulletin No. 206, dated October 13, 1987, or later JCAB approved revisions.

Alternate means of compliance with this AD may be used if approved by the Director-General of Civil Aviation Bureau.

- 3. Remarks
- 3.1 This AD becomes effective on November 9, 1987.
- 3.2 Mitsubishi Service Bulletin No. 206, dated October 13, 1987, and later JCAB approved revisions pertain to this subject.