

KU-KEN- 93

No.TCD- 645-70

Date March 24, 1970

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: NAMC Model YS-11 Airplanes, except those equipped with reinforced NLG pistons (P/N 41302-5) for Model YS-11A Airplanes .

2. Compliance required as indicated

As cracks were found on the torque arm lug fillet of the nose landing gear piston (P/N 41302 or 41302-3), accomplish the followings immediately after the effective date of this AD, unless already accomplished.

2.1 Inspect the fillet area of the torque arm lug of the nose landing gear piston (P/N 41302 or 41302-3) for cracks in accordance with NAMC Service Bulletin No. 32-130, dated March 2, 1970.

2.2 If cracks are found, modify or replace the piston as necessary in accordance with the Service Bulletin prescribed above.

Japan Civil Aviation Bureau	No. TCD - 645-70	Sheet 2
3. Remarks		
3.1 Effective date: April 10, 1970		
3.2 NAMC Service Bulletin No. 32-130, dated March 2, 1970.		