

KU-KEN- 843

No.TCD- 1094-75

Date Jan. 13, 1975

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

## Mitsubishi Model

1. Applies to: MU-2B-20/-25:S/N 201 thru 311 (except S/N 285, 291, 301, 305 and 309) MU-2B-30/-35:S/N 541 thru 650 (except S/N 559, 612, 632, 645 and 648)

2. Compliance required as indicated

To prevent the failure of the flap jack screw, unless already accomplished, within 50 hours in service after the effective date of this AD, comply with the instructions of Mitsubishi MU-2 Service Bulletin No. 167 dated Nov. 26, 1974 or the later JCAB approved revisions.

3. Remarks

- 3.1 Effective Date: Feb. 10, 1975

- 3.2 Mitsubishi MU-2 Service Bulletin No. 167 dated Nov. 26, 1974 or the later JCAB approved revisions pertain to this subject.