

KU-KEN- 509

No.TCD- 1202-75

Date Aug. 25, 1975

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

Mitsubishi

1. Applies to: MU-2B, -10, -15, -20, -25: S/N 004 thru. 318
MU-2B, -30, -35: S/N 501 thru. 654

2. Compliance required as indicated

To prevent the failure of the latches between engine nacelle upper door and side door, unless already accomplished, at the first scheduled inspection after the effective date of this AD, comply with the instructions 1. and 2. of Mitsubishi MU-2 Service Bulletin No. 171A dated July 14, 1975 or the later JCAB approved revisions.

3. Remarks

- 3.1 Effective date: September 20, 1975
- 3.2 Mitsubishi MU-2 Service Bulletin No. 171A dated July 14, 1975 or the later JCAB approved revisions pertain to this subject.