TCF-50-001-1E-1

KU-KEN-266	No.TCD-3393-91

Date March 19, 1991

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to : MITSUBISHI MU-2 series : S/N 8 through 347 (except S/N 313 and 321)
: S/N 501 through 696 (except S/N 652 and 661)

2. Compliance required as indicated , unless already accomplished.

To ensure the operation of anti-ice/deice systems, prior to next flight in icing condition or within the next 100 hours time-in-service, whichever occurs first, after the effective date of this AD, inspect the anti-ice/deice systems, and replace or repair deficient system as necessary, in accordance with MHI Service Bulletin No.212 dated November 28,1990.

3. Remarks

3.1 Effective Date : March 3, 1991.
3.2 Mitsubishi Service Bulletin No.212 dated November 28,1990 pertains to this subject.