

KU - KEN - 840

No. TCD - 2598 - 86

Date August 28, 1986

Japan Civil Aviation Bureau

TAIKUSEI - KAIZEN - TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to Fuji Model FA-200 series airplanes: S/N 101 and sub, or those modified by Fuji Service Bulletin FAS-032 dated March 16, 1971.

2.

Compliance is required as indicated, unless already accomplished. To prevent the possible loss of fuel from the vent system resulting from incorrect operation of fuel Selector valve, within 50 hours time in service after the effective date of this AD or before December 31, 1986 whichever occurs first, modify the fuel selector valve in accordance with Fuji Service Bulletin No 200-7, dated August 8, 1986.

Alternate means of compliance with this AD may be used, if approved by the Director General of Civil Aviation Bureau.

3. Remarks

3.1 This AD becomes effective on October 3, 1986.

3.2 Fuji Service Bulletin No200-7 dated August 8, 1986 pertains to this AD.