

KU-KEN- 444

No.TCD- 631-70

Date Jan. 13, 1970

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Model FUJI FA-200 series airplanes

2. Compliance required as indicated

To prevent a malfunction of the fuel quantity indicator due to failure of the transmitter, check and replace, as necessary, fuel quantity indicator and transmitter, unless already accomplished, in accordance with FUJI HEAVY INDUSTRIES SERVICE BULLETIN NO. FAS-005 or later JCAB approved revisions within the next 50 hours' time in service.

3. Remarks:

3.1 Effective date: January 13, 1970.

3.2 FUJI HEAVY INDUSTRIES SERVICE BULLETIN NO. FAS-005 covers this subject.