

KU-KEN- 729

No.TCD-1272-75

Date Nov. 14, 1975

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Mitsubishi Model MU-2B-30/-35: S/N 501 thru 585

2. Compliance required as indicated

To prevent the failure of support (P/N 030A-38824) of MLG forward door actuating mechanism, unless already accomplished, at the first scheduled inspection after the effective date of this AD, and thereafter at every 100-hour inspection, comply with the instruction of Mitsubishi MU-2 Service Bulletin No. 172 dated July 25, 1975 or the later JCAB approved revisions.

3. Remarks

3.1 Effective Date December 20, 1975

3.2 Mitsubishi MU-2 Service Bulletin No. 172 dated July 25, 1975 or later JCAB approved revisions pertain to this subject.