

TCF-50-001-1E

KU-KEN- 369

No.TCD- 1328-76

Date July 1, 1976

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Mitsubishi model MU-2B series airplanes.  
S/N: 008 ~ 038, 101 ~ 119 and 134

2. Compliance required as indicated

To prevent the possible fire hazard in the rear baggage compartment, accomplish the following.

Unless already accomplished, within 100 hours time in service after the effective date of this AD, install heatproof material around the engine bleed air tubings in accordance with Mitsubishi MU-2 Service Bulletin No. 070C dated January 7, 1976 or later JCAB approved revisions.

3. Effective Date: July 20, 1976

4. Mitsubishi MU-2 Service Bulletin No. 070C dated January 7, 1976 pertains to this subject.