

KU-KEN- 659

No.TCD-1370-76

Date Oct. 18, 1976

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Mitsubishi
MU-2B-25/-26: S/N 239 thru 328 (except 313, 321)
MU-2B-30/-35/-36: S/N 501, 504, 548 thru 673
(except 652, 661)

2. Compliance required as indicated

To prevent the tip tank fuel from entering into the strobe light, unless already accomplished, within the next, 100 hours time in service after the effective date of this AD, comply with the instructions 1. and 2. of Mitsubishi MU-2 Service Bulletin No. 174 dated Sep. 29, 1976 or the later JCAB approved revisions.

3. Remarks

3.1 Effective date: Nov. 16, 1976

3.2 Mitsubishi MU-2 Service Bulletin No. 174 dated Sep. 29, 1976 or the later JCAB approved revisions pertain to this subject.