

KU-KEN- 728

No.TCD- 1379-76

Date Nov. 8, '76

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: MITSUBISHI MU-2B-25/26: S/N 005, 239 thru.
347 inclusive (except 313, 327)

2. Compliance required as indicated

To prevent heat damage to the aft engine nacelle and adjacent structure caused by combustion of fuel entrapped in the aft engine nacelle, unless already accomplished, within the next 200 hours time in service after the effective date of this AD, install Tadpole Tapes (P/N 016A-13380-3) on nacelle tails in accordance with the INSTRUCTIONS part of Mitsubishi Service Bulletin No. 177 dated Oct. 22, 1976 or later JCAB approved revisions.

3. Remarks

3.1 Effective date: Dec. 6, 1976

3.2. Mitsubishi Service Bulletin No. 177 dated Oct. 22, 1976
or later JCAB approved revisions pertain to this subject.