

KU-KEN-344

No.TCD-1209-75

Date June 16, 1975

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Mitsubishi MU-2 Series airplanes

2. Compliance required as indicated

To prevent the failure of the nose landing gear shimmy damper, unless already accomplished, before the first flight after the effective date of this AD, comply with the instructions of Mitsubishi MU-2 Service Bulletin No. 169 dated Apr. 18, 1975 or the later JCAB approved revisions.

3. Remarks:

3.1. Effective date: JULY 10, 1975

3.2. Mitsubishi MU-2 Service Bulletin No. 169 dated Apr. 18, 1975 or the later JCAB approved revisions pertain to this subject.