Risk Assessment Rigging Jib Arm in Studio



The people that might be harmed: Studioworks employees, contractors, public, artists

HAZARD	CONTROL
 Awkward body position. Heavy loads. Trapped hands and fingers. Incorrect assembly leading to failure. Incorrectly balance arm. Toppling over whilst moving. Handling lead weights. 	 Follow safe manual handling procedures. Use two people to lift camera onto arm or break onto components. Use competent operators. Check balance before unpinning. Only move between areas/studios with wheels fully spread and arm locked down. Lead weights should be coated. If damaged and lead exposed use gloves, or wash hands after handling.

File: Rigging Jib Arm in Studio

Version: Version 1.1

Last Reviewed: 05/07/2023